



Photo 1 – Still photo from security camera video, as the helicopter touches down

Photo courtesy of FAA



Photo 2 - Tail boom

Photo courtesy of FAA



Photo 3 – Cracked tail boom

Photo courtesy of FAA




Photo 4 – Cracks

Photo courtesy of FAA