



Photo 1 – Accident Site



Photo 2 – Airplane, Right Side



Photo 3 – Engine



Photo 4 – Oil filter Element




Photo 5 – No. 1 Connecting Rod



Photo 6 – No. 1 Cylinder Disassembled



Photo 7 – Inside No. 1 Cylinder



Photo 8 – Intake Valve



Photo 9 – Intake Valve Fracture Surface