



Photo 1 – Helicopter at accident scene (Photo provided by FAA)



Photo 2 - Helicopter at accident scene (Photo provided by FAA)



Photo 3 - Helicopter at accident scene (Photo provided by FAA)



Photo 4 – Overall view of wreckage during postaccident examination (NTSB Photo)



Photo 5 – Tail boom and tail rotor during postaccident examination (NTSB Photo)



Photo 6 – Engine, fuselage cage, and gearbox during postaccident examination (NTSB Photo)



Photo 7 – Rotor mast and rotor head during postaccident examination (NTSB Photo)



Photo 8 - First magneto during postaccident examination (NTSB Photo)



Photo 9 – Second magneto during postaccident examination (NTSB Photo)



Photo 10 – Photo of powerlines running along the north side of 240th St. (Photo courtesy of ThePerryNews.com)



Photo 11 - Photo of powerlines running along the north side of 240th St. (Photo courtesy of ThePerryNews.com)