



Photo 1 – Front view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – Left side view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 3 – Right side view of the airplane at the accident site (courtesy of the Federal Aviation Administration).



Photo 4 – View of the left wing at the accident site (courtesy of the Federal Aviation Administration).



Photo 5 – View of the empennage at the accident site (courtesy of the Federal Aviation Administration).




Photo 6 – View of the cut open engine oil filter (courtesy of Wentworth Aircraft, Inc.).



Photo 7 – View of the cut open engine oil filter (courtesy of Wentworth Aircraft, Inc.).



Photo 8 – View of the cut open engine oil filter (courtesy of Wentworth Aircraft, Inc.).