



Photo 1 – Airplane at Accident Site Left Side (Source: FAA)



Photo 2 – Airplane at Accident Site Right Side (Source: FAA)



Photo 3 - Fuel Contamination Found in Left Wing Tank Fuel Sample (Source: FAA)