



Photo 1 – View of the left side of the airplane (courtesy of the Federal Aviation Administration).



Photo 2 – View of the damage sustained to the left propeller (courtesy of the Federal Aviation Administration).



Photo 3 – View of the damage sustained to the left flap (courtesy of the Federal Aviation Administration).



Photo 4 – View of the substantial damage sustained to the left wing (courtesy of the Federal Aviation Administration).



Photo 5 – View of the substantial damage sustained to the left wing (courtesy of the Federal Aviation Administration).



Photo 6 – View of the cockpit (courtesy of the Federal Aviation Administration).