



Photo 1 – Flight Path (Photo courtesy of Burlington PD)



Photo 2 – Accident Site (Photo courtesy of Burlington PD)



Photo 3 – Left Side of Airplane (Photo courtesy of Burlington PD)



Photo 4 – Forward View of Airplane (Photo courtesy of Burlington PD)



Photo 5 – Right Side of the Airplane (Photo courtesy of Burlington PD)



Photo 6 – View of Alternator – Missing Drive Belt



Photo 7 – Replaced Alternator Drive Belt



Photo 8 – Failed Alternator Belt