



**Photo 1 – Accident Site (FAA Photo)**



**Photo 2 – Left Wing (FAA Photo)**



**Photo 3 – Engine**



**Photo 4 – Carburetor Heat Shroud -- Duct**



**Photo 5 – Carburetor Heat Shroud -- Duct**



**Photo 6 – Carburetor Heat Shroud -- Muffler**



**Photo 7 – Exhaust Duct**



**Photo 8 – Carburetor Heat Duct -- Shroud**



Photo 9 – Oil Filter



| CRUISE RPM |      |      |
|------------|------|------|
|            | 65%  | 75%  |
| S.L.       | 2250 | 2375 |
| 4000       | 2350 | 2490 |
| 8000       | 2440 | 2600 |

Photo 10 - Tachometer