



Photo 1 – View towards the beginning of the crash path through the corn stalks (FAA photo)



Photo 2 – Point of impact (FAA photo)



Photo 3 – The wreckage of N444TW (FAA photo)



Photo 4 – The empennage (foreground) and cabin area (background) (FAA photo)



Photo 5 – Inverted cabin area totally consumed by fire (FAA photo)



Photo 6 – The turbocharger (FAA photo)



Photo 7 – Propeller hub and inverted engine (FAA photo)



Photo 8 – Propeller blade “A” (FAA photo)



Photo 9 – Parts of propeller blade “B” (FAA photo)



Photo 10 – Propeller blade “C” (FAA photo)