



Photo 1 – View through the corn stalks at the wreckage of N444TW (FAA photo)




Photo 2 – Another view of the wreckage of N444TW (FAA photo)



Photo 3 – Severed empennage in foreground, cabin area in background (FAA photo)



Photo 4 – Engine and left wing (FAA photo)