



Photo 1 – Airplane Wreckage



Photo 2 – Airplane Wreckage after Recovery to Hangar



Photo 3 – Oil Line



Photo 4 – Chaffed Oil Line