



Photo 1 – Aerial Photo of Accident Site (Operator Photo)



Photo 2 - Main Wreckage at Accident Site, Right Side (Air Tractor Photo)



Photo 3 – Main Wreckage at Accident Site, Left Side (Air Tractor Photo)



Photo 4 - Airplane Flight Path Angle Through Corn (Air Tractor Photo)



Photo 5 - Propeller



Photo 6 - Propeller Blade



Photo 7 - Propeller Blade