



Photo 1 – Wreckage -Left Side (FAA Photo)



Photo 2 – Tail Section (FAA Photo)



Photo 3 – Engine at Accident Site (FAA Photo)



Photo 4 – Propeller and Spinner (FAA Photo)



Photo 5 – Engine – Rear View (FAA Photo)