



Photo 1 – Airplane




Photo 2 – Exemplar Locking Pin Assembly



Photo 3 – Accident Locking Pin Assembly