



Photo 1 – Aerial view of the accident site (courtesy of the Chicago Rockford International Airport).



Photo 2 – Aerial view of the accident site (courtesy of the Chicago Rockford International Airport).



Photo 3 – Aerial view of the accident site (courtesy of the Chicago Rockford International Airport).



Photo 4 – Front view of the fuselage at the accident (courtesy of Textron Aviation).



Photo 5 – Left side view of the fuselage at the accident site (courtesy of Textron Aviation).



Photo 6 – Rear view of the fuselage at the accident site (courtesy of Textron Aviation).



Photo 7 – Right side view of the fuselage at the accident site (courtesy of Textron Aviation).



Photo 8 – View of the wreckage being recovered at the accident site (courtesy of Textron Aviation).



Photo 9 – View of the cockpit during the wreckage layout.



Photo 10 – View of the two engines during the wreckage layout.



Photo 11 – View of the fuselage and the wing remains during the wreckage layout.



Photo 12 – View of the fuselage and wing remains during the wreckage layout.