



Photo 1 – Overview of the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the aircraft next to the fence (courtesy of the Federal Aviation Administration).



Photo 3 – Close up view of the aircraft next to the fence (courtesy of the Federal Aviation Administration).



Photo 4 – View of the fuselage (courtesy of the Federal Aviation Administration).



Photo 5 – View of the wing and the fuselage (courtesy of the Federal Aviation Administration).



Photo 6 – View of the fuselage (courtesy of the Federal Aviation Administration).




Photo 7 – View of the engine (courtesy of the Federal Aviation Administration).



Photo 8 – View of the propeller (courtesy of the Federal Aviation Administration).



Photo 9 – View of the ignition system in the cockpit (courtesy of the Federal Aviation Administration).



Photo 10 – View of the handheld radio and headset that the pilot utilized (courtesy of the Federal Aviation Administration).