

TIME

SERVICE

Technician of Repair

Date: 09/10/2020 **Hours:** Tach 885.7 TT 5352.34

Tail#: N104RK

Make: Beech

Model: A36

S/N: E-1450

ELT op's checked ok per FAR 91.207d. Jacked aircraft. Checked and serviced wheels and brakes, resealed left brake caliper. Gear extension and retract tested ok per ABS Landing Gear Inspection Checklist, all tensions checked ok. Greased gear. Lubed controls and checked cable tensions. Cleaned fuel screen. Replaced fuel vent hose in left wheel well. Installed Challenger Air Filter in accordance with STC SA01669CH, see 337 this date. I certify that this aircraft has been inspected in accordance with an annual inspection following Beech MM checklist and is determined to be in airworthy condition.

Name: Robert Gloris

Co: Lakeview Aviation

Cert: [REDACTED]

Sign [REDACTED]

10/14/2020

Date: 09/10/2020 **Hours:** Tack 885.7 smoh 194.8

Tail#: N104RK

Make: Continental

Model: IO-550-B

S/N: 834702R

Changed oil and filter, filter cut and inspected and no metal noted. Service with Phillips 20W50 and 8 oz camguard. Cleaned and gapped spark plugs. Checked mag timing. Cleaned fuel screen. Replaced engine air filter, see 337 this date.

Compression check, all 76/80+. Op's and leak checked ok. I certify that this engine is approved for return to service following the work performed during a 100 hr/Annual inspection and is determined to be in airworthy condition.

Name: Robert Gloris

Co: Lakeview Aviation

Cert: [REDACTED]

Sign [REDACTED]

10/14/2020