



Photo 1 – View of airplane from front left (NTSB Photo)



Photo 2 – View of left wing (NTSB Photo)



Photo 3 – View of right wing (NTSB Photo)



Photo 4 – View of tail surfaces (NTSB Photo)



Photo 5 – View of engine during examination (NTSB Photo)



Photo 6 – View of carburetor after removal from airplane (NTSB Photo)



Photo 7 – Front view of engine during examination (NTSB Photo)



Photo 8 – View of right side of airplane (NTSB Photo)