



Photo 1 – Accident airplane in August 2019 (Courtesy of Soaring Aviation)



Photo 2 – Accident site (Courtesy of Delta County Sheriff's Office)



Photo 3 - Accident site (Courtesy of Delta County Sheriff's Office)



Photo 4 - Accident site (Courtesy of Delta County Sheriff's Office)



Photo 5 – Left side of engine



Photo 6 – Left side of engine



Photo 7 – Right side of engine



Photo 8 – Bottom of engine with oil sump pan removed