



Photo 1 – Wreckage Left Side (FAA Photo)



Photo 2 – Wreckage Top of Wings (FAA Photo)



Photo 3 – Blocked Crankcase Breather Port (FAA Photo)