

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN21LA035

METEOROLOGICAL DATA

ACCIDENT

Location: Crystal Beach, Texas
Date: October 26, 2020
Time: 1410 central daylight time
Airplane: Piper PA-28-140; Registration No. N32458

METEOROLOGICAL DATA

Weather Station

Scholes International Airport at Galveston (KGLS)
Galveston, Texas, USA
29.2653333° North Latitude
-94.8604167° West Longitude
5.6 ft mean sea level (airport field elevation)

Distance To Accident Site: 15 nautical miles
Direction To Accident Site: 044° True

Meteorological Aerodrome Report (METAR)

METAR KGLS 261852Z 07010KT 10SM FEW019 BKN038 OVC060 26/21 A2995 RMK AO2
SLP143 T02610211=

SPECI KGLS 261905Z 08012KT 10SM BKN008 BKN020 OVC042 26/21 A2995 RMK AO2
T02560211=

--- Accident Occurred at 1910 UTC (1410 CDT) ---

SPECI KGLS 261924Z 08010KT 10SM BKN010 BKN020 OVC042 26/21 A2995 RMK AO2
T02610211=

METAR KGLS 261952Z 11010KT 10SM BKN010 BKN020 OVC042 27/21 A2994 RMK AO2
SLP138 T02670211=

Terminal Area Forecast (TAF)

TAF KGLS 261733Z 2618/2718 10011G21KT P6SM BKN050 FM270700 08011KT
P6SM BKN040 FM271200 08012KT P6SM BKN030=