YEAR: 2020 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7-26	285.6			I certify that this aircraft has been inspected on 7-26-2020 in accordance with the scope and detail of Appendix D to part 43 and was found to be in a condition for safe operation. [redacted] LSRM-A-[redacted]

11/06/2020 13:01

YEAR: 2020 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7-26	285.6		285.6	R&R tailwheel tire, valve stem and wheel bearings. tail wheel tire Carlisle 4 Ply 9x3.50-4 NHS. R&R flap handle assy. w/ new updated ver. Check flaps for proper ops. & full deployment. Brakes & Main wheel bearings will need to be serviced at next annul.
				[redacted]

11/06/2020 13:09

YEAR: 2020 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7-26	285.6			R&R (8) sparkplugs due to lead fouling. Changed Oil & filter w/ Aeroshell sport 4+ & Rotax oil filter P/N# R825-016 (New style). Preformed dynamic Sync on Carbs. Raised idle to 1800 rpm. lapped cyl.# valve cover & replaced o-ring. Test ran engine, checked for leaks Non found.
				[redacted]
				LSRM-[redacted]
[redacted]				

YEAR: DATE	RECOR TACH TIME

11/06/2020 13:09