



Photo 1 – View of the accident site (courtesy of the Federal Aviation Administration).



Photo 2 – View of the right side of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 3 – View of the rear of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 4 – View of the front of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 5 – View of the left side of the inverted airplane (courtesy of the Federal Aviation Administration).



Photo 6 – Right side view of the airplane after it was recovered.



Photo 7 – Left side of the airplane after it was recovered.



Photo 8 – Rear view of the airplane after it was recovered.



Photo 9 – Rear view of the engine after the airplane was recovered.



Photo 10 – Front view of the propeller after the airplane was recovered.