

Specialist's Factual Report – Attachment 2

Image of the FAA form 6030-1 maintenance log for the F46 AWOS
applicable to November 2020.

METEOROLOGY

CEN21LA055

*Submitted by: Mike Richards
NTSB, AS-30*

or Inspect
y sensor
rs. Use

fication
r uncovered
and verify t

d place the v
value display
3% of the s
rator frequen

14	2300	10	Arrived on site for annual inspection.	JR
	2305	50	Completed inspection IAW manufacturer's instructions.	JR
	2350	41	AWOS verified.	JR
14	2355	10	Depart site.	JR
October 2020				
22	2145	10	Arrived on site for annual inspection w/FAA "FC".	JR
	2150	50	Completed inspection IAW manufacturer's instructions.	JR
	2255	41	AWOS verified.	JR
22	2300	10	Depart site.	JR
November 2020				
13	2215	10	Arrived on site to troubleshoot AWOS wheels, inaccurate	JR
	2220	50	Aligned wheel sensor with true south marker IAW Omm/MOU.	JR
	2245	41	AWOS verified.	JR
13	2250	10	Depart site.	JR
LAST ENTRY				
DATE		SIGNATURE OF SECTOR MANAGER/DESIGNEE		SIGNATURE OF MAINTENANCE TECHNICIAN
				13 Nov 2020 [Redacted]