



Photo 1 – Airplane at Accident Site Rear View (Source: FAA)



Photo 2 – Airplane at Accident Site Front View (Source: FAA)



Photo 3 – Airplane at Accident Site Side View (Source: FAA)



Photo 4 – Tires Marks at End of Runway 16 (Source: FAA)




Photo 5 – Right Main Antiskid Marks on Runway 16 (Source: FAA)




Photo 6 – Left Main Antiskid Marks on Runway 16 (Source: FAA)