



Photo 1 – Accident Airplane



Photo 2 – Accident Airplane on site

photo courtesy of FAA



Photo 3 - View of accident airplane on site

photo courtesy of FAA




Photo 4 - Engine




Photo 5 – Oil level



Photo 6 – Remote mounted oil filter



Photo 7 – Inside oil filter – metal contaminants noted




Photo 8 – Oil fill hole – metal observed



Photo 9 – Remote mount for oil filter



Photo 10 – Top of oil filter adapter




Photo 11 – Front of engine where oil filter lines connect