



Photo 1 – Main Wreckage (photograph provided by FAA)



Photo 2 – Separated Tail Boom (photograph provided by FAA)



02/09/2021

Photo 3 – Separated Tail Boom (photograph provided by MD Helicopters)



Photo 4 – Separated Tail Boom (photograph provided by MD Helicopters)



Photo 5 – Main Rotor System (photograph provided by MD Helicopters)



Photo 6 – Instrument Panel (photograph provided by MD Helicopters)



Photo 7 – Instrument Panel (photograph provided by MD Helicopters)