



Photo 1 – Accident Site (FAA Photo)



Photo 2 – Accident Site (FAA Photo)



Photo 3 – Accident Site (FAA Photo)



Photo 4 – Accident Site (FAA Photo)



Photo 5 – Left Wing (FAA Photo)



Photo 6 – Left Wing Leading Edge (FAA Photo)



Photo 7 – Right Wing (FAA Photo)



Photo 8 – Right Main Landing Gear (FAA Photo)