



Photo 1 – View of the wreckage in the field (courtesy of the Federal Aviation Administration).



Photo 2 – View of the fuselage in the field (courtesy of the Federal Aviation Administration).



Photo 3 – View of the right rear skid tube (courtesy of the Federal Aviation Administration).