



**Photo 1: Accident Site (Source: Clayton County Sheriff's Office)**



**Photo 2: Engine (Source: Federal Aviation Administration)**



**Photo 3: Crankcase (Source: Federal Aviation Administration)**



**Photo 4. Top Engine Cowl (Source: Federal Aviation Administration)**



**Photo 5: Bottom Engine Cowl (Source: Federal Aviation Administration)**



**Photo 6: Oil Breather Tube (Source: Federal Aviation Administration)**



**Photo 7: Oil Breather Tube Whistle Slot (Source: Federal Aviation Administration)**



**Photo 8: Crankcase Nose Seal (Source: Federal Aviation Administration)**