



Photo 1 – Helicopter in a field after wire strike



Photo 2 – Damage to main rotor blade



Photo 3 - Damage to main rotor blade



Photo 4 - Damage to main rotor blade



Photo 5 - Damage to main rotor blade



Photo 6 - Damage to main rotor blade