



Photo 1 - Helicopter at Accident Site (Coffey County Sherriff's Office Photo)



Photo 2 - Aft Tailboom and Fenestron (Airbus Helicopters Photo)



Photo 3 - Aft Tailboom (Airbus Helicopters Photo)



Photo 4 - Engine Before Removal (NTSB Photo)




Photo 5 - Engine Mounted in Test Cell (NTSB Photo)