



Photo 1 – Aerial view of accident site (Courtesy of Sheriff's Office)



Photo 2 – Aerial view of accident site (Courtesy of Sheriff's Office)



Photo 3 – Front left side of airplane (Courtesy of Air Tractor)



Photo 4 – Right rear of airplane (Courtesy of Air Tractor)




Photo 5 – Right wing (Courtesy of Air Tractor)



Photo 6 – Engine and propeller (Courtesy of Air Tractor)