



Photo 1 – Helicopter at Accident Site (KHP Photo)



Photo 2 – Upper Wire Cutter (Romanucci Blandin Photo)



Photo 3 – Lower Wire Cutter (Romanucci Blandin Photo)