



Photo 1 – View of front of airplane at accident site (Photo courtesy of FAA)



Photo 2 – Side view of airplane at accident site (Photo courtesy of FAA)



Photo 3 – View of the airplane aft fuselage at site (Photo courtesy of FAA)



Photo 4 – View of right wing showing buckling (Photo courtesy of FAA)