



Photo 1 – Accident airplane on runway



Photo 2 - Accident airplane on runway



Photo 3 – Right wing damage



Photo 4 – Cockpit and landing gear handle position




Photo 5 – Inside of landing gear handle




Photo 6 – Landing gear handle, mid travel position




Photo 7 – Landing gear handle, retracted position