

On Scene Photos

Courtesy of the Federal Aviation Administration



Figure 1: Overview of Debris Path



Figure 2: View of Airplane from Above

On Scene Photos

Courtesy of the Federal Aviation Administration



Figure 3: Portion of the Airplane in the Trees

Intentionally left blank. Please proceed to the next page.

On Scene Photos

Courtesy of the Federal Aviation Administration



Figure 4: Overview of the Main Wreckage

Intentionally left blank. Please proceed to the next page.

On Scene Photos

Courtesy of the Federal Aviation Administration



Figure 5: Left side of the Airplane



Figure 6: Close up of Tree in relation to Left side Fuselage

On Scene Photos

Courtesy of the Federal Aviation Administration



Figure 7: Empennage



Figure 8: Right side of the Airplane

On Scene Photos

Courtesy of the Federal Aviation Administration



Figure 9: Cabin area and Instrument Panel

END.

Submitted by: Samantha Link