



Photo 1 – Airplane at accident site viewed from front right (FAA Photo)



Photo 2 – Airplane at accident site viewed from left rear (FAA Photo)



Photo 3 – Photo of airplane during postaccident examination (NTSB Photo)



Photo 4 – Engine during postaccident examination (NTSB Photo)