



Photo 1: Accident Site (Source – Federal Aviation Administration)

Inside view of #4 cylinder. looking down bore. Exhaust valve missing. Valve seat turned sideways in exhaust port.




Photo 2: Exhaust Valve (Source – Federal Aviation Administration)