



Photo 1 – Left Wing, Bottom (Photo Provided by Federal Aviation Administration)




Photo 2 - Left Wing, Top (Photo Provided by Federal Aviation Administration)



Photo 3 – Left Wing Spar Damage (Photo Provided By Pilot)