

## Postaccident Photos N77365




*Figure 1: Forward Left side of Airplane*




*Figure 2: Right Side of Airplane*

# Postaccident Photos N77365



*Figure 3: Upper Right Wing Skin Wrinkling*



*Figure 4: Vertical Stabilizer*

END.

Submitted by Samantha Link