



Photo 1 – Completed airplane prior to accident (Photo courtesy of pilot's son)



Photo 2 – Canopy hinge and latching (Photo courtesy of pilot's son)



Photo 3 – Recovered airplane components (Photo courtesy of FAA)



Photo 4 – Airplane tail components. (Photo courtesy of FAA)



Photo 5 – Wing components (Photo courtesy of FAA)




Photo 6 – Left canopy hinge (Photo courtesy of FAA)



Photo 7 – Canopy bow components (Photo courtesy of FAA)