



**Photo 1 – Glider at Accident Site (Photo Provided by Federal Aviation Administration)**



**Photo 2 – Glider at Accident Site (Photo Provided by Federal Aviation Administration)**



**Photo 3 – Left Wing Damage (Photo Provided by Federal Aviation Administration)**