



Photo 1 – Accident Overview (Photo & Redaction by Michigan State Patrol)



Photo 2 – Damage to Left Wing (Photo from FAA)