



Photo 1 – Blue Main Rotor Blade Starflex Fracture




Photo 2 - Blue Main Rotor Blade Starflex Fracture



Photo 3 – Fractured Tail Rotor Driveshaft




Photo 4 - Fractured Tail Rotor Driveshaft