

On Scene Photos
Courtesy of the Pilot's Family



Figure 1: Gyroplane Recovery



Figure 2: Left side of Gyroplane

On Scene Photos
Courtesy of the Pilot's Family



Figure 3: Overall View of Gyroplane



Figure 4: Damage to the Rotor Mast