



Photo 1 – Front view of the airplane after the accident (courtesy of the Federal Aviation Administration).



Photo 2 – Close up front view of the substantial damage sustained to the left wing after the accident (courtesy of the Federal Aviation Administration).



Photo 3 – Close up rear view of the substantial damage sustained to the left elevator (courtesy of the Federal Aviation Administration).



Photo 4 – Close up rear view of the tailwheel (courtesy of the Federal Aviation Administration).