



Photo 1 - Airplane at Accident Site, Left (FAA Photo)



Photo 2 - Airplane at Accident Site, Right (FAA Photo)






Photo 4 - Inside No. 2 Cylinder (NTSB Photo)



Photo 5 - Exhaust Valve Stem Fracture Surface (NTSB Photo)