



Photo 1 – Airplane viewed from right (NTSB Photo)



Photo 2 – Airplane viewed from front (NTSB Photo)



Photo 3 – Airplane viewed from left (NTSB Photo)



Photo 4 – Airplane viewed from rear (NTSB Photo)



Photo 5 – Engine during examination (NTSB Photo)



Photo 6 – View showing one prop blade intact (NTSB Photo)



Photo 7 – Separated prop blades (Photo courtesy of AMF Aviation)



Photo 8 – Carburetor during examination (NTSB Photo)



Photo 9 – E-Mag ignition during examination (NTSB Photo)




Image 10 – Plot of entire flight (NTSB Image)




Image 11 – Final portion of flight (NTSB Image)