



Photo 1 – Aerial view of the accident site (courtesy of the Noble County Sheriff's Office).



Photo 2 – View of the accident site, looking to the north.



Photo 3 – View of the accident site, looking to the east.



Photo 4 – View of the accident site, looking to the south.



Photo 5 – View of the accident site, looking to the west.



Photo 6 – View of the airframe and the engine.



Photo 7 – View of the airframe and the engine.



Photo 8 – View of the airframe and the engine.



Photo 9 – View of the tailboom.



Photo 10 – View of the main rotor blades.



Photo 11 – View of the engine (courtesy of Rolls-Royce).



Photo 12 – View of the engine (courtesy of Rolls-Royce).